10/24/24, 6:32 PM Print View

# **Enforcement Report - Week of October 23, 2024**

# **Class III Biologics Event**

**Event ID:** 95385

Status: Ongoing

**Recall Initiation Date:** 06/25/2024

Center Classification Date:

10/11/2024

Recalling Firm:

Immucor, Inc. 3130 Gateway Dr

Peachtree Corners, GA 30071-1106

**United States** 

**Distribution Pattern:** 

AL, AR, AZ, CA, FL, GA, HI, IA, IL, IN, KS, KY, LA, MA, MD, MI, MN, MO, MS, NC, NH, NJ, NV, NY, OH, OK, PA, RI, SC, TN, TX, UT, VA, VT, WA, WI, WV

**Product Type:** 

**Date Terminated:** 

Voluntary / Mandated:

Voluntary: Firm initiated

**Initial Firm Notification of Consignee or Public:** 

Biologics

N/A

N/A

### **Associated Products**

## Product Description:

Reagent Red Blood Cells

#### Product Quantity:

218 kits

### Reason for Recall:

Immucor has detected that some kits of Panocell-10, Ficin treated exhibit an unexpected dark color (hemolysis) and darkening of the red blood cells. Immucor has confirmed fungal growth in the vials where the hemolysis and darkening of the red blood cells has been observed. Fungal contamination may lead to erroneous test results.

#### Recall Number:

B-0510-2024

#### Code Information:

Lot 19919E

# **Class III Biologics Event**

Event ID:

95386

Status:

Ongoing

Recall Initiation Date:

06/25/2024

Center Classification Date:

10/15/2024

**Recalling Firm:** 

Immucor, Inc. 3130 Gateway Dr

Peachtree Corners, GA 30071-1106

**United States** 

**Product Type:** 

Biologics

**Date Terminated:** 

N/A

**Voluntary / Mandated:** Voluntary: Firm initiated

**Initial Firm Notification of Consignee or Public:** 

N/A

10/24/24, 6:32 PM Print View

#### **Distribution Pattern:**

AZ, CA, CO, CT, FL, GA, HI, IA, IL, IN, KY, MA, MD, MI, MN, MO, ND, NH, NJ, NM, NY, OH, OK, OR, PA, SC, TN, TX, VA, and WA

# **Associated Products**

#### Product Description:

Reagent Red Blood Cells

#### Product Quantity:

149

#### Reason for Recall:

Immucor has detected that some kits of Panocell-10 exhibit an unexpected dark color (hemolysis) and darkening of the red blood cells. Immucor has confirmed fungal growth in the vials where the hemolysis and darkening of the red blood cells has been observed. Fungal contamination may lead to errongous test results

**Product Type:** 

**Date Terminated:** 

Voluntary / Mandated:

Voluntary: Firm initiated

Initial Firm Notification of Consignee or Public:

**Biologics** 

N/A

N/A

#### Recall Number:

B-0511-2024

#### Code Information:

lot number 21934

# **Class III Biologics Event**

Event ID:

95387

Status:

Ongoing

**Recall Initiation Date:** 

06/04/2024

**Center Classification Date:** 

10/16/2024

#### Recalling Firm:

Immucor, Inc.

3130 Gateway Dr

Peachtree Corners, GA 30071-1106

**United States** 

#### **Distribution Pattern:**

AK, AL, AR, AZ, CA, CO, FL, GA, HI, IA, IL, KS, LA, MA, MD, ME, MI, MN, MO, MS, NC, ND, NJ, NM, NV, NY, OH, OK, OR, PA, SC, TN, TX, VA, WA, WI, and WV

### **Associated Products**

### **Product Description:**

Reagent Red Blood Cells

# Product Quantity:

591

#### Reason for Recall:

Immucor has detected that some kits of Panoscreen I, II & III exhibit an unexpected dark color (hemolysis) and darkening of the red blood cells. Immucor has confirmed fungal growth in the vials where the hemolysis and darkening of the red blood cells has been observed. Fungal contamination may lead to erroneous test results.

#### Recall Number:

B-0512-2024

### Code Information:

Lot number 17845